


GPMP 2008	GRID SQUARE(S) 101.X30-X31	ARCHITECTURE	CONTEXT 21902
1. Material	1. Mud		
2. Size of materials	2. 37cm to 40cm x 17cm to 19cm		
3. Finish	3. Regular courses		
4. Coursing/bond	4. the western side is stretcher / the eastern side have one row stretcher 20cm x 40cm / and 2 rows header 30cm x 15cm		
5. Form	5. wall		
6. Direction of faces	6. North-South		
7. Orientation	7. East-West		
8. Dimensions	8. 98cm to 65cm wide x 5.00m long		
9. Associated collapse	9. N/A		
10. Founds, cuts & fills	10. N/A 11. N/A		
11. Repaired	12. N/A 13. N/A there is a plaster in Eastern and Western faces		
12. Associated floors	14. N/A		
13. Plastered	15. Sandy mud bricks		
14. Wall core	16. Mud + Sand + ocean ceramics and V. acca Lime Stone pebbles		
15. Types of brick (%)	17. See above		
16. Composition of bricks			
17. Dimensions of bricks (sample of three)			

Stratigraphic Matrix 	Abuts 21900	Above
	Abutted by	Below
	Bonded into	
	Contiguous with	

INTERPRETATION	Enclosing	Internal	External
Reason for decay	East-West wall which abuts <21900> N-S wall		
Indications of original dimensions	and Meets <21901> N-S wall		
Indications of original functions			

Associated contexts:			
Context Same As:			
Drawing Nos:		Samples	
Photographs	Findings		
Roll	Bag No.	Type	
Frames		Building Complex:	
B+W		Phase	
CS			
DP			
CP	Site Book Pages	Checked	Initials Date



T.B.M:- 18.54
 B.S :- 2.58
 L.O.C: 21.12

F# 21902

π	RL
1- 2.98	18.14
2- 3.15	17.97
3- 3.13	17.99