
AREA:	GRID SQUARE (S):	I	RDINATES:	· 	INITIALS & DA	ΓE:	FEATURE No.:	
KKt-N	201 D14 201 E14	N E		MFMH 1-2-2012		33472		
FEATURE T	YPE (For example wa	II) staircase,	bench, found	ation	Full extent visil	ole in p	lan:	
structure, p	elatform etc.):	all			(YI		NO	
1. Dimensions (in metres)			Length: Width:		· · · · · · · · · · · · · · · · · · ·		it:	
		5.35	.35 m 0.60 m 0.02 m			m		
	naterial(s) used		mudbrick					
3. Coursing	(form of construction) two	two Coarses of mudbrick					
4. Orientation	on	N-	N-5					
5. Associate	ed collapse							
6. Cut & fill t	feature #'s							
7. Repaired?	?				,			
8. Associate	ed floors							
9. Surface tr paint, mould	reatments? E.g. plaste	er,						
	_					<u> </u>		
	ne component	0.40 n	n by o.	15 m		_		
11. Bonding	material	Sand	19 Silt			•		
12. Excavate	ed	Yes(No	Not 6	* Cal	vated			
Mini stratigr	aphic matrix		Abuts: <33	471	Same a	s:		
			Abutted by:		Associa	ated fea	ntures:	
	33472		Bonded into) :				
	33471		Contiguous with:					
Discussion a	and interpretation:		<u> </u>					
it's au	rall of mulbric	k (N-S), it con	sists	of Two coun	ses,	the western	
face is	headers, and the	in the e	astern on	e is s	itrechers. H	meas	sives	
5.35 m	length by 0.60	m width	· It ab	uts +	he wall <	3347	7# >.	
forms +	the western he eastern wee	wan g le of th	e space	(113	11301 , 1136 1 03) .	2) an	d the It	
it is clear	My that thewal	Uis in o	e bad Ends	tion	because son	e pa	its are	
traded an	ed the crushed	line ston	e appears	frequ	ently_			

Remember: do not just draw the architectural feature in isolation. Show how it relates to surrounding features and include details of surface treatments, repairs/modifications/damage, bonding material(s), and associated cuts. Annotate all aspects of the feature or use a Drawing Key. Measurements must be included for all aspects of the feature and surrounding features.



<u>Profile</u> Sketch - State direction the elevation of the feature being drawn is facing e.g. 'West Facing Elevation of Feature If feature was drawn in section then include the grid co-ordinates and elevations.

Photo No.'s: 512737, 512738			
Structure No.: house (B)			
Matrix Phase:			